



**Lower Plaquemines Parish
Mean High Water Marks**

Survey Date

February 4, 2006

by

3001 Inc.

LA 110= 12.17' ft NAVD 88(2004.65)



LA 111 = -0.54' ft NAVD 88(2004.65)

= THE FLOOR IN THE ROOM THAT HAD THE HWM MARKED ON THE WALL. DUE TO THE GUTTING OF THE INSIDE OF THE BUILDING THE HWM WAS GONE. SO WE JUST SHOT THE FLOOR NEAR THE LOCATION OF THE HWM. JEFF AND NANCY POWELL ARE ALREADY AWARE OF THIS.



LA 112 = 7.01' ft NAVD 88(2004.65)




LA 113 = 6.92' ft NAVD 88(2004.65)



LA 114 = 7.56' ft NAVD 88(2004.65)



LA 115 = 12.10' ft NAVD 88(2004.65)



LA 116 = 13.865' ft NAVD 88(2004.65)



LA 117 = 13.925' ft NAVD 88(2004.65)



LA 118 = 14.06' ft NAVD 88(2004.65)



LA 119 = 15.48' ft NAVD 88(2004.65)



LA 120 = 16.23' ft NAVD 88(2004.65)



LA 121 = 14.81' AND 15.35' ft NAVD 88(2004.65) -- THERE WAS A LARGE PAINTED MARK ON THE STEEL BEAM. THESE 2 ELEV'S REPRESENT THE TOP AND THE BOTTOM OF THE PAINT MARK.

